

APPENDIX B
PHOTOGRAPHS

Photo 1



Vertical Bank of the Antelope Creek Entrenchment

Photo 2



Antelope Valley Entrenchment

Photo 3



Palen Dam and Reservoir

Photo 4



The Eroding Bottom and Banks of Antelope Valley Creek

Photo 5



Tributary Stream Channel Caught in the Antelope Valley Road
Inside Ditch

Photo 6



The Top of The Area Excavated to Supply Material For Palen Dam
Note Dewatering of the Meadow Above and the Sudden Drop in the Valley

Photo 7



Palen Reservoir Bypass Diversion Dam
Note Its Deteriorated State

Photo 8



Failing Outlet Channel of Palen Reservoir

Photo 9



West-side Ditch and Antelope Valley Creek

Photo 10




Bear Valley Creek at the Bottom of an Entrenchment
Note No Floodplain so Erosion Forces Against Banks is High

Photo 11



Bear Valley Creek Immediately Upstream of Sierra Brooks Drive

Photo 12



Section of the Last Chance Creek Gully Obliterated Using the Plug-and-Pond Technique (*Note, Late Summer Conditions in this Seasonal Streamflow Section*)

Photo 13



Remnant Channel Streamflow and Flooding onto the Historic Floodplain
Humbug Creek Upstream of Delleker on the Michelson Ranch